



876 Otter Creek Road
Oregon, Ohio 43616-3518
Phone: (419) 698-3500 or (800) 537-0426
Fax: (419) 698-8663
Website: www.envirosafeservices.com

June 9, 2011

Ms. Lynn Ackerson
Ohio EPA, NWDO
347 North Dunbridge Road
Bowling Green, OH 43402

**Re: Envirosafe Services of Ohio, Inc.
 Oregon, Lucas County, Ohio
 EPA Identification Number: OHD 045 243 706; Ohio Permit Number: 03-48-0092
 May 2011 Progress Report**

Dear Ms. Ackerson:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), Envirosafe Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning May 1, 2011 and ending May 31, 2011.

Corrective Measures Study ("CMS"):

Project Activities and Summary of Findings to Date:

During this reporting period, CMS activities included the following:

1. Follow-up on April 26, 2011 conference call (draft CMS Report comments) including review of Ohio EPA notes and provision of clarifying comments; and
2. Response to Ohio EPA on why solar panels on closed units are not an option at this time.

Summary of All CMS-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

There is nothing to report in association with this topic for this reporting period.

Changes in Personnel:

There have been no changes to CMS personnel during this reporting period.

Projected Work:

During the next reporting period it is anticipated that the following activities will occur:

1. Evaluation of CMS Report comments.

2.

Corrective Measures Implementation (“CMI”):

Project Activities:

During this reporting period, CMI activities included the following:

1. The following is documentation that SWMUs 5, 6, and 7 are in compliance with maintaining an inward gradient. The leachate level at each SWMU’s interior piezometers has an average head potential at least 1-foot lower than the average liquid potential in the established perimeter shallow till wells, as identified in Table 1.0 of the OMPM Plan. All interior piezometers and exterior wells were measured on May 30, 2011.

							Average	Difference (out-in)
SWMU 5 - Central	TLL: 557.1							
Interior Piezometers	PZ-5	PZ-6	PZ-7	PZ-21	PZ-22	PZ-23	575	
	583.33	570.73	569.41	573.56	572.51	577.71		
Exterior Wells	F-1S	G-1S	MR-1SA	MR-4S	MR-5S	MR-7S	582	8
	585.78	585.42	583.51	584.46	578.46	577.09		
<hr/>								
SWMU 5 - West	TLL: 564.9							
Interior Piezometers	PZ-13						569	
	569.40							
Exterior Wells	MR-2S	MR-6S					576	7
	577.36	574.68						
<hr/>								
SWMU 6	TLL: 566.9							
Interior Piezometers	PZ-1	PZ-2	PZ-3	PZ-15	PZ-16		582	
	583.53	586.27	578.01	578.88	582.47			
Exterior Wells	H-2S	SW-1S	SW-2S	SW-3S	T-8S		589	7
	588.96	586.97	586.56	588.05	592.30			
<hr/>								
SWMU 7	TLL: 570.8							
Interior Piezometers	PZ-9	PZ-10	PZ-11	PZ-18	PZ-19	PZ-20	583	
	590.38	587.06	564.48	589.00	585.18	583.78		
Exterior Wells	T-5S	T-8S	T-15S	T-43S				6
	591.45	592.30	589.97	583.53		589		
<hr/>								
Deep Wells 04/01/11	G-10A: 574		MR-03D: 569		SW-02D: 572			

2. On May 12, 2011 ESOI submitted a construction completion report and permit modification request updating the OMPM Plan to address the recently completed leachate extractions systems modifications;
3. Engineering was completed and utility trenching was initiated for additional wells and pumps at SWMUs 5, 6 and 7 in order to achieve the TLL by the compliance dates; and

4. Continued operation and monitoring of the leachate extraction systems on SWMUs 5, 6, and 7.

Summary of All CMI-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

See the November 2010 progress report for issues previously reported regarding recovery well RW-4. There is nothing new to report in association with this topic for this reporting period.

Projected Work:


During the next reporting period it is anticipated that the following activities will occur:

1. ESOI will order supplies for additional pumps, controls, etc. and contract with a driller to install the additional leachate extraction wells outlined in the enhancement plan (and the additional explosive gas vents on SWMU 5);
2. Continued operation and maintenance of the leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact Stephen DeLussa at (215) 659-2001 ext. 15.

Sincerely,



Douglas E. Roberts
President

cc: Stephen DeLussa, Envirosource Technologies, Inc.
Ken Humphrey, ESOI
Michael Terpinski, Ohio EPA, NWDO, DERR
Edwin Lim, Ohio EPA, Columbus, DERR
Darla Peelle, Ohio EPA, Columbus, PIC
Hak Cho, USEPA Region 5
Michael Momenee, The Mannik & Smith Group
Mark Nielsen, ENVIRON International Corp.