



876 Otter Creek Road
Oregon, Ohio 43616-3518
Phone: (419) 698-3500 or (800) 537-0426
Fax: (419) 698-8663
Website: www.envirosafeservices.com

May 6, 2011

Ms. Lynn Ackerson
Ohio EPA, NWDO
347 North Dunbridge Road
Bowling Green, OH 43402

**Re: EnviroSAFE Services of Ohio, Inc.
Oregon, Lucas County, Ohio
EPA Identification Number: OHD 045 243 706; Ohio Permit Number: 03-48-0092
April 2011 Progress Report**

Dear Ms. Ackerson:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), EnviroSAFE Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning April 1, 2011 and ending April 30, 2011.

Corrective Measures Study ("CMS"):

Project Activities and Summary of Findings to Date:

During this reporting period, CMS activities included the following:

1. ESOI responded to Ohio EPA regarding a message forwarded to them from USEPA about a public request for placement of a paper copy of the CMS Report in the Oregon Branch of the Toledo-Lucas County Public Library. Paper copies of the report are available at ESOI and Ohio EPA (Bowling Green and Columbus). In addition, the report is available online through ESOI's website (www.envirosafeservices.com/correctiveaction.html). The corrective action webpage was established in January and a public notice introducing it was sent to the facility mailing list. These documents can be accessed, reviewed, copied, and printed from any computer including those located at the library. An appointment can be made to view paper copies of these documents at ESOI or either of Ohio EPA's offices. Requests for additional copies of specific pages can be accommodated. ESOI believes these mechanisms provide ample public access in both paper and electronic formats; and
2. Conference call on April 26, 2011 among ESOI, ENVIRON and Ohio EPA regarding Ohio EPA's draft comments on the CMS Report.

Summary of All CMS-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

There is nothing to report in association with this topic for this reporting period.

Changes in Personnel:

There have been no changes to CMS personnel during this reporting period.

Projected Work:

During the next reporting period it is anticipated that the following activities will occur:

1. Evaluation of April 26, 2011 discussion regarding Ohio EPA's draft comments on the CMS Report and scheduled follow-up call with Ohio EPA.

2.

Corrective Measures Implementation (“CMI”):

Project Activities:

During this reporting period, CMI activities included the following:

1. The following is documentation that SWMUs 5, 6, and 7 are in compliance with maintaining an inward gradient. The leachate level at each SWMU’s interior piezometers has an average head potential at least 1-foot lower than the average liquid potential in the established perimeter shallow till wells, as identified in Table 1.0 of the OMPM Plan. All interior piezometers and exterior wells were measured on April 13, 2011.

							Average	Difference (out-in)	
SWMU 5 - Central	TLL: 557.1								
Interior Piezometers	PZ-5	PZ-6	PZ-7	PZ-21	PZ-22	PZ-23			
	583.11	571.34	570.08	575.11	573.19	576.24	575		
Exterior Wells	F-1S	G-1S	MR-1SA	MR-4S	MR-5S	MR-7S		8	
	585.71	587.08	583.46	583.71	577.78	576.77	582		
<hr/>									
SWMU 5 - West	TLL: 564.9								
Interior Piezometers	PZ-13								
	568						568		
Exterior Wells	MR-2S	MR-6S						7	
	576.85	574.11					575		
<hr/>									
SWMU 6	TLL: 566.9								
Interior Piezometers	PZ-1	PZ-2	PZ-3	PZ-15	PZ-16				
	583.71	586.42	578.16	578.9	582.43		582		
Exterior Wells	H-2S	SW-1S	SW-2S	SW-3S	T-8S			6	
	589.88	584.98	586.29	588.32	590.12		588		
<hr/>									
SWMU 7	TLL: 570.8								
Interior Piezometers	PZ-9	PZ-10	PZ-11	PZ-18	PZ-19	PZ-20			
	590.5	582.03	564.37	588.87	585.19	584.84	583		
Exterior Wells	T-5S	T-8S	T-15S	T-43S				6	
	590.89	590.12	588.58	584.06			588		

2. ESOI evaluated the need for additional actions at SWMUs 5, 6 and 7 in order to achieve the TLL by the compliance dates. A proposal for additional wells and pumps has been presented to and accepted by Ohio EPA. Contracting and project activities will begin in May; and

3. Continued operation and monitoring of the leachate extraction systems on SWMUs 5, 6, and 7.

Summary of All CMI-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

See the November 2010 progress report for issues previously reported regarding recovery well RW-4. There is nothing new to report in association with this topic for this reporting period.

Projected Work:


During the next reporting period it is anticipated that the following activities will occur:

1. ESOI will order supplies for additional pumps, controls, etc. and contract with a driller to install the additional leachate extraction wells outlined in the enhancement plan (and the additional explosive gas vents on SWMU 5);
2. ESOI will submit a construction completion report and permit modification updating the OMPM Plan to address the recently completed modifications to the leachate extractions systems; and
3. Continued operation and maintenance of the leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact Stephen DeLussa at (215) 659-2001 ext. 15.

Sincerely,


Douglas E. Roberts
President

cc: Stephen DeLussa, Envirosource Technologies, Inc.
Ken Humphrey, ESOI
Michael Terpinski, Ohio EPA, NWDO, DERR
Edwin Lim, Ohio EPA, Columbus
Darla Peelle, Ohio EPA, Columbus, PIC
Hak Cho, USEPA Region 5
Michael Momenee, The Mannik & Smith Group
Mark Nielsen, ENVIRON International Corp.